


FLAT HEADS



$$\begin{aligned} r(\text{mm}) &= 20-100 \\ h_1(\text{mm}) &\geq 20-100 \\ H(\text{mm}) &= h_1 + r + t \end{aligned}$$

Stainless Steel